

## VISUAL TANK INSPECTION REPORT

	ETT-113 Hercules Shipyard / Freeport, Normal Butanol	Техав	Your Reference: FP/97-5223  Date: April 23, 1997
Tank			
Number	1C	2C	3C
Tank <u>Coating</u>	Mild Steel	Mild Steel	Mild Steel
Last			
Cargo	Cyclohexane	<u>Cyclohexane</u>	Cyclohexane
Second Last			
Cargo	<u> </u>		· · · · · · · · · · · · · · · · · · ·
Chird Last			
Cargo			
Visual Cleanliness			
Accepted *	Accepted	Accepted	Accepted
isual Cleanliness Rejected *			
lime/Date	1845	1845	1845
Inspected	04/23/97	04/23/97	04/23/97
ethod said to have	e been used to clean tanks:	Tanka #1 Center	, #2 Center and #3 Center: Stripped and blown dry.

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

\* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb\_Brett